

School Name:		Schodack Central School District										
Lab ELAP ID# 10350		Analysis Method:			EPA 200.8 REV 5.4							
Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-01	3/9/2021	Kitchen bathroom	Bathroom faucet	Initial	0.016	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-01-S	4/14/2021	Kitchen bathroom	Bathroom faucet	Post	0.008	4/27/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-02	3/9/2021	All-gender bathroom in café	Bathroom faucet	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-03	3/9/2021	Bottle filler in café	Bottle filler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-04	3/9/2021	Water fountain in café	Water cooler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-05	3/9/2021	Kitchen hand sink	Kitchen faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-06	3/9/2021	Kitchen 3-bay left	Kitchen faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-07	3/9/2021	Kitchen 3-bay middle	Kitchen faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-08	3/9/2021	Kitchen 3-bay right	Kitchen faucet	Initial	0.024	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-08-S	4/14/2021	Kitchen 3-bay right	Kitchen faucet	Post	0.013	4/27/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-09	3/9/2021	Hallway fountain outside kitchen	Water cooler	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-10	3/9/2021	Girl's locker room - left	Bathroom faucet	Initial	0.018	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-KF-10-S	4/14/2021	Girl's locker room - left	Bathroom faucet	Post	0.009	4/27/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-11	3/9/2021	Girl's locker room - right	Bathroom faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-IM-12	3/9/2021	Sports ice machine	Ice machine	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-13	3/9/2021	Sports utility sink	Utility sink	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-14	3/9/2021	Fountain outside girl's locker room	Water cooler	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-15	3/9/2021	Fountain outside boy's locker room	Water cooler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-16	3/9/2021	Boy's locker room - left	Bathroom faucet	Initial	0.007	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-17	3/9/2021	Boy's locker room - right	Bathroom faucet	Initial	0.010	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-18	3/9/2021	Nurse bathroom	Bathroom faucet	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-NS-19	3/9/2021	Nurse sink by beds	Nurse faucet	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-NS-20	3/9/2021	Nurse treatment sink	Nurse faucet	Initial	0.008	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-21	3/9/2021	Boy's coach bathroom	Bathroom faucet	Initial	0.005	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-22	3/9/2021	Girl's coach bathroom	Bathroom faucet	Initial	0.005	3/17/2021				

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-23	3/9/2021	Trophy lobby fountain - left	Water cooler	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-24	3/9/2021	Trophy lobby fountain - right	Water cooler	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-25	3/9/2021	Trophy lobby boy's bathroom Far left	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-26	3/9/2021	Trophy lobby boy's bathroom Middle left	Bathroom faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-27	3/9/2021	Trophy lobby boy's bathroom Middle right	Bathroom faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-28	3/9/2021	Trophy lobby boy's bathroom Far right	Bathroom faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-29	3/9/2021	Trophy lobby girl's bathroom Far left	Bathroom faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-30	3/9/2021	Trophy lobby girl's bathroom Middle left	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-31	3/9/2021	Trophy lobby girl's bathroom Middle right	Bathroom faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-32	3/9/2021	Trophy lobby girl's bathroom Far right	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-33	3/9/2021	Room 136	Classroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-34	3/9/2021	Room 137 - far left	Classroom faucet	Initial	0.005	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-35	3/9/2021	Room 137 - middle left	Classroom faucet	Initial	0.004	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-36	3/9/2021	Room 137 - middle right	Classroom faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-37	3/9/2021	Room 137 - far right	Classroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-38	3/9/2021	Band room 139	Classroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-39	3/9/2021	Downstairs bottle filler	Bottle filler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-WC-40	3/9/2021	Downstairs water fountain	Water cooler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-41	3/9/2021	Downstairs girl's bathroom - left	Bathroom faucet	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-42	3/9/2021	Downstairs girl's bathroom - right	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-43	3/9/2021	Downstairs boy's bathroom - left	Bathroom faucet	Initial	0.003	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-44	3/9/2021	Downstairs boy's bathroom - right	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-0-BF-45	3/9/2021	Basement bathroom sink	Bathroom faucet	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-CF-46	3/9/2021	Room 213 - left	Classroom faucet	Initial	0.008	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-CF-47	3/9/2021	Room 213 - right	Classroom faucet	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-CF-48	3/9/2021	Room 215	Classroom faucet	Initial	0.001	3/17/2021				

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-WC-49	3/9/2021	Upstairs bottle filler	Bottle filler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-WC-50	3/9/2021	Upstairs water fountain	Water cooler	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-51	3/9/2021	Room 222 - left	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-52	3/9/2021	Room 222 - right	Bathroom faucet	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-53	3/9/2021	Room 223 - left	Bathroom faucet	Initial	0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-54	3/9/2021	Room 223 - right	Bathroom faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-55	3/9/2021	Room 228	Bathroom faucet	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-BF-56	3/9/2021	Faculty all-gender bathroom	Bathroom faucet	Initial	<0.001	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-2-KF-57	3/9/2021	Room 226	Kitchen faucet	Initial	0.002	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-58	3/9/2021	Room 145 - right	Classroom faucet	Initial	0.006	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-BF-59	3/9/2021	Room 145 - bathroom	Bathroom faucet	Initial	0.006	3/17/2021				
Capital Region Environmental	Maple Hill Jr/Sr High	MHH-1-CF-60		Room 145 - left	Classroom faucet	Initial			Not functional			

School Name:		Schodack Central School District									
Lab ELAP ID# 10350			Analysis Method:			EPA 200.8 REV 5.4					
Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken		
Capital Region Environmental	Castleton Elementary	CES-1-WC-01	3/9/2021	Café bottle filler	Bottle filler	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-WC-02	3/9/2021	Café fountain	Water cooler	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-KF-03	3/9/2021	Kitchen hand sink	Kitchen faucet	Initial	0.010	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-KF-04	3/9/2021	Kitchen 3-bay - left	Kitchen faucet	Initial	0.010	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-KF-05	3/10/2021	Kitchen 3-bay - right	Kitchen faucet	Initial	0.005	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-IM-06	3/9/2021	Kitchen ice machine	Ice machine	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-BF-07	3/9/2021	Café bathroom	Bathroom faucet	Initial	0.003	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-BF-08	3/9/2021	Room 109	Bathroom faucet	Initial	0.003	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-09	3/9/2021	Room 109	Classroom faucet	Initial	0.006	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-10	3/9/2021	Room 109	Drinking fountain	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-WC-11	3/9/2021	Fountain at end of hall by gym - left	Water cooler	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-WC-12	3/9/2021	Fountain at end of hall by gym - right	Water cooler	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-BF-13	3/9/2021	Righthand gym bathroom	Bathroom faucet	Initial	0.002	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-BF-14	3/9/2021	Lefthand gym bathroom	Bathroom faucet	Initial	0.002	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-15	3/9/2021	Room 123	Drinking fountain	Initial	0.002	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-16	3/9/2021	Room 114	Drinking fountain	Initial	0.002	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-17	3/9/2021	Room 114	Classroom faucet	Initial	0.012	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-18	3/9/2021	Room 125	Drinking fountain	Initial	0.003	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-19	3/9/2021	Room 125	Classroom faucet	Initial	0.012	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-BF-20	3/9/2021	Room 112	Bathroom faucet	Initial	0.002	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-21	3/9/2021	Room 112	Classroom faucet	Initial	0.032	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-21-S	4/14/2021	Room 112	Classroom faucet	Post	0.004	4/27/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-22	3/9/2021	Room 112	Drinking fountain	Initial	<0.001	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-23	3/9/2021	Room 126	Classroom faucet	Initial	0.023	3/18/2021			
Capital Region Environmental	Castleton Elementary	CES-1-CF-23-S	4/14/2021	Room 126	Classroom faucet	Post	0.004	4/27/2021			
Capital Region Environmental	Castleton Elementary	CES-1-DW-24	3/9/2021	Room 126	Drinking fountain	Initial	<0.001	3/18/2021			

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Castleton Elementary	CES-1-DW-25	3/9/2021	Room 111	Drinking fountain	Initial	0.003	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-26	3/9/2021	Room 111	Classroom faucet	Initial	0.009	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-BF-27	3/9/2021	Room 111	Bathroom faucet	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-DW-28	3/9/2021	Room 128	Drinking fountain	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-29	3/9/2021	Room 128	Classroom faucet	Initial	0.008	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-BF-30	3/9/2021	All-gender bathroom across from 102	Bathroom faucet	Initial	0.002	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-DW-31	3/9/2021	Room 107	Drinking fountain	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-32	3/9/2021	Room 107	Classroom faucet	Initial	0.007	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-BF-33	3/9/2021	Room 107	Bathroom faucet	Initial	0.009	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-34	3/9/2021	Room 105	Classroom faucet	Initial	0.008	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-DW-35	3/9/2021	Room 105	Drinking fountain	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-DW-36	3/9/2021	Room 104	Drinking fountain	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-37	3/9/2021	Room 104	Classroom faucet	Initial	0.006	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-BF-38	3/9/2021	Room 104	Bathroom faucet	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-BF-39	3/9/2021	Room 159	Bathroom faucet	Initial	0.004	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-NS-40	3/9/2021	Nurse room 158 - main	Nurse sink	Initial	0.005	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-NS-41	3/9/2021	Nurse back room	Nurse sink	Initial	0.029	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-NS-41-S	4/14/2021	Nurse back room	Nurse sink	Post	0.002	4/27/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-CF-42	3/9/2021	Room 180	Classroom faucet	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-WC-43	3/9/2021	Fountain next to room 140 - left	Water cooler	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-WC-44	3/9/2021	Fountain next to room 140 - right	Water cooler	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-CF-45	3/9/2021	Room 146	Classroom faucet	Initial	0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1A-CF-46	3/9/2021	Room 148	Classroom faucet	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-0-KF-47	3/9/2021	Basement faculty room	Kitchen faucet	Initial	0.011	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-0-BF-48	3/10/2021	Basement faculty room bathroom	Bathroom faucet	Initial	0.033	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-0-BF-48-S	4/14/2021	Basement faculty room bathroom	Bathroom faucet	Post	<0.001	4/27/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-49	3/9/2021	Band room	Classroom faucet	Initial	0.016	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-49-S	4/14/2021	Band room	Classroom faucet	Post	0.001	4/27/2021				

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Castleton Elementary	CES-2-WC-50	3/9/2021	2nd floor bottle filler	Bottle filler	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-2-WC-51	3/9/2021	2nd floor water fountain	Water cooler	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-2-BF-52	3/9/2021	All-gender bathroom across from 207	Bathroom faucet	Initial	0.002	3/23/2021				
Capital Region Environmental	Castleton Elementary	CES-2-CF-53	3/9/2021	Room 240	Classroom faucet	Initial	0.004	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-2-DW-54	3/9/2021	Room 280	Drinking fountain	Initial	<0.001	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-2-CF-55	3/9/2021	Room 237	Classroom faucet	Initial	0.012	3/18/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-56	3/9/2021	Room 123	Classroom faucet	Initial	0.160	3/23/2021				
Capital Region Environmental	Castleton Elementary	CES-1-CF-56-S	4/14/2021	Room 123	Classroom faucet	Post	0.003	4/27/2021				

School Name:		Schodack Central School District											
Lab ELAP ID# 10350			Analysis Method:			EPA 200.8 REV 5.4							
Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken				
Capital Region Environmental	Schodack District Office	SDO-1-CF-1	3/10/2021	Room 104 - Left Sink	Classroom Faucet	Initial	0.011	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-2	3/10/2021	Room 104 - Right Sink	Classroom Faucet	Initial	0.001	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-WC-3		Fountain Next to Custodian Room A	Water Fountain				Temporarily Out of Service				
Capital Region Environmental	Schodack District Office	SDO-1-BF-4	3/10/2021	Room 110	Bathroom Faucet	Initial	<0.001	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-5	3/10/2021	Room 114	Classroom Faucet	Initial	0.001	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-6	3/10/2021	Room 109	Classroom Faucet	Initial	0.001	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-7	3/10/2021	Room 111	Classroom Faucet	Initial	0.008	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-8	3/10/2021	Room 118	Classroom Faucet	Initial	<0.001	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-9	3/10/2021	Room 113	Classroom Faucet	Initial	0.003	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-10	3/10/2021	Room 115	Classroom Faucet	Initial	0.006	3/18/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-11	3/10/2021	Room 122	Classroom Faucet	Initial	0.002	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-KF-12	3/10/2021	Room 122 Kitchen Faucet	Sprayer	Initial	0.002	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-13	3/10/2021	Room 203	Classroom Faucet	Initial	0.024	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-13-S	4/14/2021	Room 203	Classroom Faucet	Post	0.008	4/19/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-14	3/10/2021	Room 205 Nurse's Bathroom	Bathroom Faucet	Initial	0.006	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-15	3/10/2021	Room 204	Classroom Faucet	Initial	0.002	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-NS-16	3/10/2021	Room 205 Nurse Hand Sink	Nurse's Sink	Initial	0.004	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-17	3/10/2021	Boys Room 206 - Far Left	Bathroom Faucet	Initial	0.006	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-18	3/10/2021	Boys Room 206 - Middle Left	Bathroom Faucet	Initial	0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-19	3/10/2021	Boys Room 206 - Middle Right	Bathroom Faucet	Initial	0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-20	3/10/2021	Boys Room 206 - Far Right	Bathroom Faucet	Initial	<0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-WC-21	3/10/2021	Fountain Left of Room 207	Water Fountain	Initial	<0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-22	3/10/2021	Room 208	Bathroom Faucet	Initial	<0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-23	3/10/2021	Girls Room 209 - Far Left	Bathroom Faucet	Initial	<0.001	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-24	3/10/2021	Girls Room 209 - Middle Left	Bathroom Faucet	Initial	0.003	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-25	3/10/2021	Girls Room 209 - Middle Right	Bathroom Faucet	Initial	0.003	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-BF-26	3/10/2021	Girls Room 209 - Far Right	Bathroom Faucet	Initial	0.010	3/23/2021					
Capital Region Environmental	Schodack District Office	SDO-1-CF-27	3/10/2021	Room 313 Sink "B"	Classroom Faucet	Initial	0.008	3/23/2021					

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Schodack District Office	SDO-1-CF-28	3/10/2021	Room 313 Sink "F"	Classroom Faucet	Initial	0.015	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-CF-29	3/10/2021	Room 313 Sink "J"	Classroom Faucet	Initial	0.016	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-CF-30	3/10/2021	Room 313 Sink "K"	Classroom Faucet	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-31	3/10/2021	Room 313 Prep Room	Classroom Faucet	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-32	3/10/2021	Room 311 CF	Classroom Faucet	Initial	0.130	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-KF-33	3/10/2021	Room 311 Sprayer	Sprayer	Initial	0.400	3/30/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-WC-34	3/10/2021	Fountain Next to 309	Water Fountain	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-35	3/10/2021	Room 309 Sink "B"	Classroom Faucet	Initial	0.020	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-CF-36	3/10/2021	Room 309 Sink "C"	Classroom Faucet	Initial	0.002	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-37	3/10/2021	Room 309 Sink "E"	Classroom Faucet	Initial	0.006	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-38	3/10/2021	Room 305 Sink- Left	Classroom Faucet	Initial	0.041	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-CF-39	3/10/2021	Room 305 Sink- Right	Classroom Faucet	Initial	0.016	3/23/2021	Taken out of servcie			
Capital Region Environmental	Schodack District Office	SDO-1-WC-40	3/10/2021	Fountain Across from Room 304	Water Fountain	Initial	0.029	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-WC-40-S	4/14/2021	Fountain Across from Room 304	Water Fountain	Post	0.001	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-41	3/10/2021	Room 304 Home Ec Sink "A"	Kitchen Faucet	Initial	0.010	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-42	3/10/2021	Room 304 Home Ec Sink "B"	Kitchen Faucet	Initial	0.013	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-43	3/10/2021	Room 304 Home Ec Sink "C"	Kitchen Faucet	Initial	0.016	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-43-S	4/14/2021	Room 304 Home Ec Sink "C"	Kitchen Faucet	Post	<0.001	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-44	3/10/2021	Room 304 Home Ec Sink "D"	Kitchen Faucet	Initial	0.007	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-45	3/10/2021	Room 304 Home Ec Sink "E"	Kitchen Faucet	Initial	0.012	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-46	3/10/2021	Room 419 Sink - Left	Bathroom Faucet	Initial	0.067	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-46-S	4/14/2021	Room 419 Sink - Left	Bathroom Faucet	Post	0.001	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-47	3/10/2021	Room 419 Sink - Right	Bathroom Faucet	Initial	0.007	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-48	3/10/2021	Room 300	Classroom Faucet	Initial	0.027	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-CF-48-S	4/14/2021	Room 300	Classroom Faucet	Post	<0.001	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-49	3/10/2021	Kitchen 3 Bay Sink - Left	Kitchen Faucet	Initial	0.002	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-50	3/10/2021	Kitchen 3 Bay Sink - Right	Kitchen Faucet	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-51	3/10/2021	Kitchen Bathroom	Bathroom Faucet	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-KF-52	3/10/2021	Kitchen Hand Sink	Kitchen Faucet	Initial	0.011	3/23/2021				

Lab ID	School Building	Sample ID#	Collection Date	Sample Location	Outlet Description	Initial/ Post	Results mg/L	Lab Report Receipt Date	Action Taken			
Capital Region Environmental	Schodack District Office	SDO-1-KF-53	3/10/2021	Kitchen 2 Bay	Kitchen Faucet	Initial	0.010	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-WC-54	3/10/2021	Fountain Next to Room 413	Water Fountain	Initial	0.004	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-WC-55	3/10/2021	Cafeteria Water Fountain	Water Fountain	Initial	0.012	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-56	3/10/2021	Main Office - Superintendent's Room	Bathroom Faucet	Initial	0.022	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-56-S	4/14/2021	Main Office - Superintendent's Room	Bathroom Faucet	Post	<0.001	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-57	3/10/2021	Boys Lockerroom - Coaches Office	Bathroom Faucet	Initial	0.002	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-WC-58	3/10/2021	Boys Lockerroom - Water Fountain	Water Fountain	Initial	0.002	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-59	3/10/2021	Boys Lockerroom Sink - Left	Bathroom Faucet	Initial	0.006	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-60	3/10/2021	Boys Lockerroom Sink - Right	Bathroom Faucet	Initial	0.005	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-WC-61	3/10/2021	Fountain Next to Room 406	Water Fountain	Initial	0.005	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-62	3/10/2021	Girl's Coach Office Bathroom	Bathroom Faucet	Initial	0.073	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-62-S	4/14/2021	Girl's Coach Office Bathroom	Bathroom Faucet	Post	0.002	4/19/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-63	3/10/2021	Girls Lockerroom Sink - Left	Bathroom Faucet	Initial	0.003	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-64	3/10/2021	Girls Lockerroom Sink - Right	Bathroom Faucet	Initial	0.008	3/23/2021				
Capital Region Environmental	Schodack District Office	SDO-1-BF-65	3/10/2021	Personel Office Bathroom	Bathroom Faucet	Initial	0.005	3/23/2021				